


















Benodigdheden -- Liste des pièces -- Requisites -- Benötigtes -- Accesorios


<p>G301</p>  <p>1x</p>	<p>L710</p>  <p>1x</p>	<p>L771</p>  <p>1x</p>
 <p>3x</p>	 <p>±11kg 1x</p>	<p>L740</p>  <p>4x</p>
<p>L760</p>  <p>5x</p>	 <p>6x 4x M10</p>	
<p>S530-V26 Ø120x2480mm 4x</p> <p>S431-H-H13 Ø120x2420mm 4x</p> <p>S540-H-V14 Ø120x2070mm 2x</p> <p>S530-Vloer-VPE 22x95x1065mm 5x</p>	<p>12x  12x230</p> <p>12x  M12</p> <p>12x  M12</p> <p>12x  M12</p> <p>90x  4,5x50</p>	




1





2



3





7

Bij droog weer moeten alle bouten en schroeven opnieuw aangespannen worden.
Par temps sec il faut resserrer régulièrement toute la visserie.
By dry and warm weather check the tightness of all bolts and screws.
Bei trockenem Wetter müssen alle Schrauben und Bolzen aufs neue angespannt werden.
Para el tiempo seco, se necesita cerrar o ajustar los tornillos y tuercas.